# **OPERATION MANUAL**

# **HEAT INDEX WBGT METER**



( (

Model: 8758

### INTRODUCTION

Thank you for purchasing the Heat Index WBGT meter. The handy meter measures air temperature, globe temperature, and humidity to give heat stress index for using in control of physical activity in hot environment to limit the danger of heat-related injuries

WBGT(wet-bulb globe temperature) was developed as a monitoring basis at US military training camps and became widespread for the use in workplaces and sports situations. It is suggested in an international standard ISO 7243 and many governments such as OSHA (US Occupational Safety & Health Administration), SMA(Sports Medicine Australia), and Japan Society for Occupational Health in establishing the permissible heat exposure limits in occupational health, sports or other physical activities. (See appendix)

The applications of the heat index can be in construction, iron and steel foundries, bricks-firing plants, glass facilities, boiler rooms, mining sites, army training, marathon, beach activities and so on.

#### Features:

- Direct measurement of the radiation effect with a brass black ball.
- Adjustable WBGT alarm threshold
- Audible beeper for heat stress monitoring
- Sensor protecting mechanism
- Easy self calibration for humidity
- PC connect for data analysis

# CONTROLS AND INDICATORS

# **LCD** display



#### Symbol indication

WBGT Wet Bulb Globe Temperature

TG Black Globe Temperature

TA Air Temperature

% Relative HumidityC/F Celsius/Fahrenheit

IN Indoor (no sun)
OUT Outdoor (full sun)

Low battery indicator

DP/REC 1888 Vain icons in these

models.

# Function Keys



Turn on and off the meter Enter alarm setting mode

Select digit in setting mode

Exit from setting mode

MODE S

Select display mode Shift IN/OUT mode

Increase value in setting

Set as non-sleep
Select °C or °F

Select Cor F

Enter RH calibration

# OPERATING INSTRUCTIONS

# 1. POWER ON/OFF

Press to turn on and turn off the meter. All indicators are shown on the LCD when power on, and then enter measuring mode.

#### 2. MEASUREMENT

Slide down the protecting sheath of sensor before measurements.



# Select display mode

The meter measures TA(Air Temp), TG (Globe Temp.), RH (Relative Humidity), and calculates WBGT. Press to select modes. An icon shows on the top to indicate the current operation mode. (Fig. A)





Fig. A

#### IN/OUT switch

To measure WBGT without or with direct sun exposure under IN/OUT modes, hold down for more than 1 second to switch.

#### Select Unit

Press ( and ) simultaneously in measuring mode to select °C or °F.

#### 3. ALARM SETTING

The meter features audible alarm to give warning for possible heat stress in the environment. When WBGT value reaches the alarm threshold, the value starts to blink with continuous beep(about 70 dB). The alarm stops when measured value falls below the threshold or the meter is turned off.

The alarm threshold is adjustable for different applications. Hold down for 2 seconds to turn on the meter and enter alarm setting. The current setting displays with a blinking digit. Press to increment the value and to select digit. After new alarm threshold is set, press for 2 seconds to return to measuring mode.

The setting range is 20.0~37.2°C (68.0~99.0°F). "OUT" will show if setting is out of range. (Fig. B)



### 4. BATTERY REPLACEMENT

appears on the LCD when battery voltage gets low. To replace battery by opening the compartment on the rear of the meter.

#### 5. AUTO POWER OFF

The meter turns off automatically after 20 minutes non-operation. To override the function, hold down and for 2 seconds to turn on the meter. The LCD will display "n" and then enter measuring mode. (Fig. C)



### 6. TRIPOD MOUNTING

The meter can fit on a tripod for long time monitoring. A built-in thread is on the rear side of the meter.

# **RH CALIBRATION**

The meter can be calibrated on the humidity by end users with 33% and 75% salt solution. The ambient condition is recommended to be at 23+/-2°C and stable humidity. Users can terminate the calibration anytime by turning off the meter.

Unscrew the black globe with sensor sheath (see pic. A) before calibration.

Follow the illustration on page 7 to recap sensor sheath after completing calibration.

Black globe with sensor sheath Sensor connector Sensor

probe

Pic. A



#### 33% calibration

Plug the sensor probe into 33% salt bottle(Pic A1), hold down , , , and buttons for 2 seconds to power on the meter until blinking "3X.X%" appears. Meter is now calibrating, and will finish in about 60 mins. when the value stops blinking.

#### Note:

Strongly recommend to use one hand to press one button, and use two fingers of the other hand to press two buttons simultaneously . This is easier for you to operate 3 keys.

#### 75% calibration

After 33% calibration, plug the sensor probe into 75% salt bottle, then press me for 2 seconds to start.


The blinking "7X.X%" shows on the screen and meter is now calibrating. Wait about 60 mins.until blinking stops ,it means the calibration is completed and meter returns to measuring mode.

### Note:

The RH value difference between the meter display and calibration standard should be within +/-0.3%, otherwise it is a failed calibration

### **CAUTION:**

Reassemble the globe with caution by fitting the pin (Pic. B) into the connector (Pic.C). It helps to position by targeting the screw holes on the sheath and the meter. Incorrect installation may damage the sensor.



# **TROUBLESHOOTING**

#### ? Power on but no display

Check whether the batteries are in good contact and correct polarity, or take out the batteries for one minute and reinstall and retry.

#### ? Calibration failure

- a.Check the battery voltage or replace
- b.Check whether the sensor is well plugged into the salt bottle and no air comes in. Check ambient condition.

#### ? Error message on the display

- E2: The value is under range. Improper sensor installation.
- E3: The value is over range.
- E4: The value is in error because of the original data. Improper sensor installation.
- E11: RH calibration error. Do the calibration again.
- E32/E33: Circuit error. Return to the vendor for repair or replacement.

### **RS232 INTERFACE**

The meter can do PC link for on-line logging and data analysis via RS232 interface and software.

The protocol is as follows.

A.9600 bps, 8 data bits, no parity.

#### B.Format

(Transmitting ASCII code by every second while meter is on.)

Wxxx.xC(F):Txxx.xC(F):Txxx.xC(F)

:Hxx.x%LRCCRLF

Note: The 1st value is WBGT, the 2nd is TA, the 3rd is TG, and the 4th is RH.

# SPECIFICATION

		8758	8778	
Black ball size		40(D)x35(H)mm	75(D)x75(H)mm	
Air Temp. range		0~50°C (32~122°F)		
Air Temp. accuracy		±0.6℃		
Globe Temp. range		0~80°C (32~176°F)		
Globe Temp.	Indoor	±2℃ (15~40℃)	±1°C (15~40°C)	
		±2.5°C (Others)	±1.5°C (Others)	
accuracy	Outdoor	±3°C (15~40°C)	±1.5℃ (15~40℃)	
accuracy		±3.5°C (Others)	±2°C (Others)	
WBGT Te	mp. range	0~50°C (32~122°F	0~50°C (32~122°F)	
WBGT Formula		Indoor/Outdoor a   WBGT=0.7WB + (   Outdoor and full   WBGT=0.7WB + (	0.3TG <b>sun:</b>	
RH range		0~100%		
RH accuracy		±3% (10~90%RH) ±5% (other range)		
Resolution		0.1℃/℉, 0.1%RH		
Response time		15 seconds typical		
Operating	g condition	0~50℃, 0~95% RH		
Storage of	condition	-20~65°C, 0~95% RH		
Meter size		40(H)x48.7(W)x254(L)mm - 8758 75(H)x75(W)x278.2(L)mm - 8778		
Battery life		1000 hours (Alkaline)		
(without beep)		250 hours (General	al purpose)	

### MATERIALS SUPPLIED

#### This package contains:

- ✓ Meter
- ✓ 2pcs AAA batteries
- ✓ Operation manual
- Plain box packaging

### Optional accessory:

- √ 33% calibration salt (VZHR33AZ)
- √ 75% calibration salt (VZHR75AZ)
  - ✓ RS232 cable and software

### WARRANTY

The meter is warranted to be free from defects in material and workmanship for a period of one year from the date of purchase. This warranty covers normal operation and does not cover misuse, abuse, alteration, neglect, improper maintenance, or damage resulting from leaking batteries. Proof of purchase is required for warranty repairs. Warranty is void if the meter has been opened.

### **RETURN AUTHORIZATION**

Authorization must be obtained from the supplier before returning items for any reason. When requiring a RA (Return Authorization), please include data regarding the defective reason, the meters are to be returned along with good packing to prevent any damage in delivery and insured against possible damage or loss.

#### **APPENDIX**

Recommendations to heat exposure level for working and physical activity!

# PERMISSIBLE HEAT EXPOSURE THRESHOLD LIMIT

Value:WBG				
Work/rest regimen (Each hour)	Light	Moderate	Heavy	
Continuous work	30°C	26.7°C	25°C	
	/86°F	/80°F	/77°F	
75% work, 25% rest	30.6°C	28°C	25.9°C	
	/87°F	/82°F	/78°F	
50% work, 50% rest	31.4°C	29.4°C	27.9°C	
	/89°F	/85°F	/82°F	
25% work, 75% rest	32.2°C	31.1°C	30°C	
	/90°F	/88°F	/86°F	

Source: ACGIH 1992(The American Conference of Governmental Industrial Hygienists)

WBGT Flag Activity Intensity

#### WBGT INDEX AND PHYSICAL EXERCISE

		Atotivity intolloity
< 80°F < 26.7°C	White	Normal activity. Caution should be taken.
80-84.9°F 26.7-29.4°C	Green	Discretion is required in planning intense physical activity.
85-87.9°F 29.4-31°C	Yellow	Intense activity for new and unacclimatized persons should be curtailed.
88-89.9°F 31-32.2°C	Red	Intense exercise must be curtailed for those with less than 12 weeks training in hot weather. Be on high alert
> 90°F > 32.2°C	Black	Cancel all outdoor exercise.

Source: Manual of Naval Preventive Medicine (NAVMED P-5010)

# Accuracy, the Zenith of Measuring / Testing Instruments!

Hygrometer.	Psychromete/	r
-------------	--------------	---

Thermometer

Anemometer

Sound Level Meter

Air Flow meter

Infrared Thermometer

K type Thermometer

K.J.T. type Thermometer

K.J.T.R.S.E. type Thermometer

pH Meter

Conductivity Meter

T.D.S. Meter

D.O. Meter

Saccharimeter

Manometer

Tacho Meter

Lux / Light Meter

Moisture Meter

Data logger

Temp./RH transmitter

Wireless Transmitter .....

More products available !

2013/08 Ver.2