## **HEAT STROKE PREVENTION METER**



## Wind speed value makes your **WBGT** more close to real climate thermo impact!



WBGT	WBGT		
indicator	87785/87782	indicator	87785/877

Green backlight (26.7~29.4°℃)

(29.4~31°€)



Red backlight (31~32.2℃)



Red flashing backlight (Above 32.2°€)

Balance Co.		
WBGT	Flag	Activity Intensity
< 80°F < 26.7°C	White	Normal activity. Caution should be taken.
80-84.9° <sup>0</sup> F 26.7-29.4°C	Green	Discretion is required in planning intense physical activity.
85-87.9°F 29.4-31°C	Yellow	Intense activity for new and acclimatized persons should be curtailed.
88-89.9°F 31-32.2°C	Red	Intense exercise must be curtailed for those with less than 12 weeks training in hot weather. Be on high alert
> 90°F > 32.2°C	Black	Cancel all outdoor exercise.

**Ordering Code** 

Source: Manual of Naval Preventive Medicine (NAVMED P-5010)

VZ87782AZ, 87782 meter VZ87785AZ, 87785 meter VZ87781ST2, salt bottles VZUSBAZM, software kit

## **Professional WBGT Monitor** 87782/87785

- ■Check Indoor/Outdoor WBGT, TA/TG/RH & wind speed
- ■Designed with capacitance type humidity sensor with dust filter to get accurate reading and extend sensor life time
- ■Model 87785 is equipped with cup type anemometer to measure wind speed from all direction
- ■Audible beeper and backlight for danger zone warning



LED

LED Alarm

















Model	87785	87782		
Windspeed range	0.5~10 m/s			
Windspeed Acc. +/-(	2% of reading +0.2) m/s			
Temp. range		50°C		
Temp. resolution	0.19	°C/°F		
Temp. accuracy	+/-0	+/-0.6°C		
Humidity. range	0.1%~	0.1%~99.9%RH		
Humidity resolution	0.1	%RH		
Humidity accuracy	+/-3%RH (at 25°C, 10~	90%RH,others +/-5%RH)		
Globe Temp. (inside black	*	80°C		
Globe Temp. Acc. Indoor:	+/-1 °C(at 15~ r: +/-1.5 °C(at 15	40°C),others1. 5 °C 5~40°C),others 2 °C		
WBGT temp. range	0~5	50°C		
WBGT Alarm Range	20-	~50°C		
Black ball size(mm)	Dia. 75,	Dia. 75, height:75		
Stabilization time	15 ~25 min	15 ~25 minutes typical		
RH% Self calibration	YE	YES		
Battery life	~100	~100hour		
LCD size (mm)	50(H)x	50(H)x32(W)		
Operation temp.	0~5	0~50°C		
Operation RH% Humidity < 80%		lity < 80%		
Storage temp.	-20~50°C			
Storage RH%	Humid	Humidity < 90%		
Dimension(mm) 310(	H)x91(diameter, windcup)	302(H)x75(W)x36.7(T)		
Weight	~350g	~300g		
Battery	AAA	AAA x4pcs		
Standard Package	andard Package Meter/Battery/Manual/Hard carry case (87785) or paper box (87782)			

## Optional



CAL. SALT BOTTLE P/N:VZ87781ST2 (33% & 75%) For 87782/87785 Calibration .



USB cable & software P/N: VZUSBAZM